

Care of paintball balls

Storage conditions

- The ideal temperature for storing marbles is between 15°C and 30°C. The relative humidity should be between 40 - 50%. Any other values outside the specified range may have an undesirable effect on the quality of the marbles.
- Keep the balls sealed in their original bags. If you leave them open, the capsules will react with the environment and become either more brittle or soften more quickly.
- If you store the balls in boxes or original bags for a longer period of time, always turn them regularly.
- Leave marbles in containers, tubes and boxes on the course only for as long as necessary.
necessary.

Cold weather tips

- When playing, if possible, leave the marbles in a warm place (e.g. in a heated car) or in another warm place).
- Balls that are stored incorrectly or exposed to cold temperatures for a long time may develop dents. But if the balls are fresh, simply return them to the correct storage temperature of 15 -30 °C and they will stretch nicely again.

Hot weather tips

Never expose marbles to direct sunlight and always put them somewhere shady and relatively cool. The biggest mistake is leaving marbles and other equipment in the sun in a parked car.

The main thing to remember is that the longer you leave your marbles in unsuitable conditions, the more likely it is that the quality of the marbles will be negatively affected. If a marble is exposed to extreme conditions (cold 0°C, hot 35°C) for even just 20 minutes, it is enough to adversely affect its quality.

RPR SHOP

WWW.RPRSHOP.CZ